



CONNECTOR
Filed: January 23, 2002
Darryl Mexic
202-293-7060

1 of 8












MIYAMOTO Q68219 STRUCTURE FOR PREVENTING FAILURE OF CONNECTOR Filed: January 23, 2002 Darryl Mexic 202-293-7060 4 of 8



MIYAMOTO
Q68219
STRUCTURE FOR PREVENTING FAILURE OF
CONNECTOR
Filed: January 23, 2002
Darryl Mexic
202-293-7060
5 of 8




MIYAMOTO Q68219 STRUCTURE FOR PREVENTING FAILURE OF CONNECTOR Filed: January 23, 2002 Darryl Mexic 202-293-7060 6 of 8



South Print from anny traine the front from the front front

2 =

MIYAMOTO Q68219 STRUCTURE FOR PREVENTING FAILURE OF CONNECTOR Filed: January 23, 2002 Darryl Mexic 202-293-7060 7 of 8



2 7

MIYAMOTO
STRUCTURE FOR PREVENTING FAILURE OF
CONNECTOR
Filed: January 23, 2002
Darryl Mexic
202-293-7060
8 of 8

